



TENAGA NASIONAL BERHAD (200866-W)

Nama Pencawang	: SSU EDELWEISS TROPICANA	BCE	: 2025-12-18	Functional Test (Plant - RCB)
Functional Location	: BPJY/PCE/J01945	RCB	: 2025-12-18	Local Test (Plant - RCB - RTU)
Kawasan	: BPJY	Work	:	Integration test (RCB - RTU - Master)
Koordinat	:	Comms	:	Commissioning Test (Plant - RTU/FTU - Master)
Jenis Pencawang	:	RTU/FTU Brand	:	DONG FANG
Jenis Comms	: DSR	RTU/FTU Serial No.	:	VCB BH0055
CAASDU	: 1255	RTU/FTU No.	:	TNB130/2024
DTU ID	:	RTU / FTU Protocol	:	IEC101
SIM CARD No	:			
IP Address	:			

SIGNAL	FEEDER												DETAILS RTU			
	J58975	J58976	J58977	J58978	J58979	J58980	J58981					RTU/FTU	BCE 1	BCE 2	SAT Form	: Ada
															Master sheet	: Ada
															As Built Drawing	: Ada
INDICATION													DETAILS PIW			
CB OPEN	✓	✓	✓	✓	✓	✓	✓								No. PIW	TNB130/2024
CB CLOSE	✓	✓	✓	✓	✓	✓	✓								Wiring List	: ADA
PROT. ALARM													DETAILS PIW			
SUPER/REMOTE	✓	✓	✓	✓	✓	✓	✓								As Built Drawing	: ADA
OVERCURRENT	✓	✓	✓		✓	✓	✓								RCB Brand	AHM
EARTHFAULT	✓	✓	✓		✓	✓	✓								RCB No.	TNB1628/2022
IRF	✓	✓	✓		✓	✓	✓								No of RCB	2
EARTH SWITCH	✓	✓	✓		✓	✓	✓								RCB 1 Serial No.	BF250217
EFI OPERATED	✓				✓	✓									RCB 2 Serial No.	BF250219
C.E.S												✓			RCB 3 Serial No.	
CHARGER ALARM													✓	✓	BCE 1 Brand	BERKAT INSAF
AC FAIL													✓		BCE 1 No.	TNB338/2024
DC LV															BCE 1 Serial No.	B22872
TCS	✓	✓	✓		✓	✓	✓									
ANALOG													No. Feeder	Feeder Name		
CT RATIO	600 / 5	600 / 5	300 / 5		600 / 5	600 / 5	600 / 5								J58975	PPU DATARAN SUNWAY CB13
															J58976	MSB TENANT 1
															J58977	TX 1000KVA
AMP 0%	✓	✓	✓		✓	✓	✓								J58978	BUS SECTION
AMP 50%	✓	✓	✓		✓	✓	✓								J58979	MCB TENANT 2
AMP 100%	✓	✓	✓		✓	✓	✓								J58980	PE DAMANSARA INDAH NO. 6
CONTROL													J58981	PMU KOTA DAMANSARA		
CB CTRL OPEN	✓	✓	✓	✓	✓	✓	✓					✓				
CB CTRL CLOSE	✓	✓	✓	✓	✓	✓	✓					✓				
EFI RESET	✓				✓	✓										

PIC Tapak : MOHD TARMIZI ALIAS PIC MASTER :